

Oil Field Environmental Incident Summary

Incident: 20140728150753 **Date/Time of Notice:** 07/28/2014 15:07

Responsible Party: PETRO-HUNT, L.L.C.

Well Operator: PETRO-HUNT, L.L.C.

Well Name: SILURIAN 19-1

Field Name: CHARLSON

Well File #: 10448

Date Incident: 7/25/2014 **Time Incident:** 10:00

Facility ID Number:

County: MCKENZIE

Twp: 153

Rng: 95

Sec: 11

Qtr:

Location Description:

Submitted By: Doug Hanson

Received By:

Contact Person: Doug Hanson
PO BOX 935
BISMARCK, ND 58502

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 2 Mile

Distance Nearest Water Well: 2 Mile

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	15	Barrels	15	Barrels	15	barrels
Other						

Description of Other Released Contaminant:

Inspected:

Written Report Received: 1/19/2016

Clean Up Concluded: 7/30/2014

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

There will be some contaminated soils at the base of the tank.

Action Taken or Planned:

The on/off switch on the pump start panel is being pinned.

Wastes Disposal Location: Liquids will go to disposal well and solids will be hauled to Prairie Disposal at Tioga.

Agencies Involved:

Updates

Date: 7/29/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a tank overflow, remained on location, within the diking, according to the report. NDIC retains oversight.